




# Protective Counter Barrier

## Product Parts

1. Frame (x1)
2. Feet (x2)
3. Optional Graphic (x1-Top)(xBottom)
4. Hook & Loop Strips



## Display Set-Up

### Step 1

Remove protective film covering the clear part of barrier. DO this by peeling back from any corner. Dispose of protective film.

### Step 2

If your display was ordered as a KIT (hardware + graphics), the Graphics (3) will come installed. IF you have ordered Graphics (3) after your purchase of hardware, adhere the graphic(s) to bottom and top of Frame (1) centered between the sides on the \*front of frame.


\*Front of frame is identified as non-routed edge and where frame is flush with clear window.

### Step 3

Attach Feet (2) to frame by aligning slots, pushing both Frame (1) and foot together until each stops.

### Optional Vertical Mount

Remove feet (2) and use Hook & Loop (4) to mount to vertical surface. Place Hook & Loop wherever most useful for your application.



## Storage & Care

To Store: Remove feet and store flat in a cool dry place.

To Clean Frame and Feet: Use soap and water.

To Clean Clear Window: Use soap and water, or hydrogen peroxide and isopropyl alcohol-based sanitizers. **DO NOT USE** cleaners or disinfectants containing Ammonia, Bleach or Alcohol. Cleaners or disinfectants containing Ammonia, Bleach or Alcohol will crack or fog the clear sheet.

Please go to [Showdowndisplays.com](http://Showdowndisplays.com) to find this product and its list of approved cleaners.